

CHANGEDEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

4620.1 CHG 3

4/9/73

Cancellation

Date: After filing

SUBJ: SCHEDULED OVERHAUL OF GROUND FACILITIES EQUIPMENT

1. PURPOSE. This change transmits an interim page change to the subject order.
2. DISTRIBUTION. This change is to be distributed to the Branch level in the Washington Headquarters Airway Facilities Service, regional Airway Facilities and Logistics Divisions and FAA Depot; normal distribution to all Airway Facilities Field Offices.
3. CHANGE. This change provides information concerning (a) the exchange period for RML Azimuth Synchro Panels, (b) E&R instructions for the synchro panels and (c) corrected FSNs for the synchro panels.
4. PAGE CONTROL
 - a. The attached interim page shall be inserted into the subject order as described in the Page Control Chart shown below without removing existing printed pages.
 - b. Both the interim pages and the affected existing pages will be replaced with revised printed pages as a part of a subsequent change to the subject order, which is now undergoing review.

PAGE CONTROL CHART

Remove Pages	Dated	Insert Pages	Dated
None		6-1, 6-2	4/9/73


J. W. COCHRAN

for Director, Airway Facilities Service

Distribution: WAF-3; RAF/LG-3; CDE-3; MAF-2
FAF-0 (Normal); AAC-480 (20 copies)

4/9/73

4620.1 CHG 3

*Paragraph 9j should be disregarded and the following information regarding RML Azimuth Synchro Panels shall apply:

The 27,000 hours of operation exchange period requirement for the below listed RML Azimuth Synchro Panels is deleted. Exchange (E&R) is on an "as-fail" basis. When effecting E&R, the radar antenna speed and the synchro speed must be specified by the requisitioning facility.

<u>Type</u>	<u>FSN</u>
CA-4315, Collins 18-RM	5820-473-0765
CA-4315A, Collins 61A1-RM	5820-325-2365**
CA-4318, Collins 21-RM	5820-325-2364**
CA-4318A, Collins 63A1-RM	5820-325-2366**
CA-4318A, Collins 63A1 for RML-4	5820-701-3366**

** Indicates revised FSN

*

INTENTIONALLY LEFT BLANK